



ORDINANCE NO. 2491-25

AN ORDINANCE RATIFYING AND CONFIRMING THE EXECUTION OF A PREVIOUSLY AUTHORIZED EXPENSE WITH RUSH TRUCKS OF HUNTELY, ILLINOIS FOR REPAIR OF TRUCK 22

BE IT ORDAINED by the Mayor and Board of Trustees of the Village of Hawthorn Woods, Illinois, that this ordinance is ratification in furtherance of a previously authorized expense with Rush Trucks of Huntley, Illinois for Repair of Truck 22. Such Agreement is by and between the Village of Hawthorn Woods and Rush Trucks., a copy of which is attached hereto as Exhibit "A", and, by this reference made a part hereof.

The foregoing Ordinance was adopted by the Village Board of the Village of Hawthorn Woods, Illinois, on July 21, 2025:

AYES: KAWCZAK, MCCARTHY, RYCHLIK, BAUSER, HURBT, LAHAN

NAYS: ☐

ABSENT AND NOT VOTING: ☐

APPROVED:
Dominick DiMaggio, Mayor

ATTEST:
Katreina Koprowski, Village Clerk

PASSED: JULY 21, 2025

APPROVED: JULY 21, 2025

PUBLISHED: JULY 21, 2025



RUSH TRK CTR OF N IL

11816 S IL RTE 47 - HUNTLEY, IL 60142

Phone: (1) 847-8025800 - Fax: (1) 847-5951

(Service Writer: Shea Dieter - Date: 5/28/2025 10:02 AM C)

Estimate #4851397 Prepared For

Village Of Hawthorn Woods

35 Old McHenry Rd., Lake Zurich, IL 600476610 (primary)

Phone: (1) 847-4385500 - Fax: () -

(VIN: 1HTWDAZR4FH666961 - Unit: 22)



Currency: USD

Unit No: 22

Village Of Hawthorn Woods

VIN: 1HTWDAZR4FH666961
Model: 7400 SFA 4X2
Engine: MAXXFORCE 9 315HP/2200 GOV
Make: International
Delivered: 1/26/2015
In Service: 10 Years 4 Months
Mileage: 18888 Eng Hrs: 2017

Recall/AFC: No

Contact Name: Todd Knoll
Position: service-primary
Phone: (847) 438-5500
E-Mail: tknoll@vhw.org
PO Number:

Operation (All Sections)	Labor Cost	Parts Cost	Core Charge	Total Cost
DIAGNOSE MISFIRE WITH BASE ENGINE ANALYSER MODULE, #6 SHOWS NO COMPRESSION	\$454.00	\$0.00	\$0.00	\$454.00
REMOVE OIL PAN AND VALVE COVER TO DETERMINE CAUSE OF FAILURE	\$1,135.00	\$0.00	\$0.00	\$1,135.00
REPLACE CYLINDER #6 (1) SEAL KIT, POWER CYLINDER (1) TUBE, TURBO OIL SUPPLY (1) PISTON KIT, SLEEVE AND RINGS 570 (34) 125152EXX (10) ZXEDRU1COOLANT (1) MSCHDWR	\$10,896.00	\$6,043.06	\$0.00	\$16,939.06
REPLACE CYLINDER HEAD, TRANSFER COMPONENTS, WILL REQUIRE NEW INTAKE MANIFOLD & #6 INJECTOR (1) HEAD, CYLINDER, ENGINE, CYLINDER W/ VALVES (1) MANIFOLD, AIR INTAKE (1) TUBE, EGR COOLER RETURN (1) TUBE, INJECTOR COOLER, INLET (1) TUBE, INJECTOR COOLER, OUTLET (18) BOLT, M8 X 1.25 X 24MM (1) INJECTOR, FUEL, I334, 570, REMAN; NEW OR REMAN: REMANUFACTURED	\$1,362.00	\$9,020.20	\$800.00	\$11,182.20

Notes: [5/28/2025 10:02 AM] - Dealer: ESTIMATE FOR REPAIRS

Parts: \$15,063.26
Core: \$800.00
Labor: \$13,847.00
Shop: \$75.00
Tax: \$0.00
TOTAL: \$29,785.26

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. AUTHORIZED BY: _____
DATE: ___/___/___

Estimate #4851397

Labor Card

Customer: Village Of Hawthorn Woods
Vehicle: 7400 SFA 4X2

VIN: 1HTWDAZR4FH666961
Unit: 22

RO: 49837022
Mileage: 18888
Date: 5/28/2025

Time: 2.0 **DIAGNOSE MISFIRE WITH BASE ENGINE ANALYSER
MODULE, #6 SHOWS NO COMPRESSION**

Variation: A2- DIAGNOSE MISFIRE WITH BASE ENGINE ANALYSER MODULE, #6 SHOWS NO COMPRESSION

Standard Operation Notes: N/A

Additional Notes: N/A

Time: 5.0 **REMOVE OIL PAN AND VALVE COVER TO DETERMINE
CAUSE OF FAILURE**

Variation: A2- REMOVE OIL PAN AND VALVE COVER TO DETERMINE CAUSE OF FAILURE

Standard Operation Notes: N/A

Additional Notes: N/A

Time: 48.0 **REPLACE CYLINDER #6**

Variation: A2- REPLACE CYLINDER #6

Standard Operation Notes: N/A

Additional Notes: N/A

Time: 6.0 **REPLACE CYLINDER HEAD, TRANSFER COMPONENTS,
WILL REQUIRE NEW INTAKE MANIFOLD & #6 INJECTOR**

Variation: A2- REPLACE CYLINDER HEAD, TRANSFER COMPONENTS, WILL REQUIRE NEW INTAKE MANIFOLD & #6 INJECTOR

Standard Operation Notes: N/A

Additional Notes: N/A